

FRANKLIN DRAIN PROFILE

NOV. 1939
 GRADE LINE
 WATER SURFACE (1939)
 CONDITION PROFILE 1939

F. B. 2519

BRIDGES

FLUME

CONDITION PROFILE AFTER CLEANING APR. 1940

Sta. 0+00 & Middle Drain 328+80

