

B.M. Elev. 3616.59 "□" Left end of cut-off wall of check in Franklin Canal at Sta. 997+46.

LEGEND

- Right Bank
- Left Bank
- High Water Surface
- High Water, end of turnout
- Natural Surface, left and right.
- Bottom of lateral.

DAUGHERTY LATERAL CONDITION PROFILE 1960

Surveyed by Taylor 10-26-60

Field Book 3161 Ysleta.

Plotted by E.R.J.

Checked by - R.C.

Revised 2-25-63 S.P.

To show R & B structures

Revised 4-5-85 EC

To show BRASS CAPS

23-503-6617

