

B.M. for this profile was destroyed when Clint Lateral Heading was rebuilt.

- LEGEND
- Right Bank
  - Left Bank
  - High Water Surface
  - High Water Surface End of Turnout
  - Bottom of Lateral

# RODRIGUEÑA LATERAL CONDITION PROFILE 1960

Surveyed by Taylor Aug. 1960.  
Nov. 1960

Field notes in Book 3149, Ysleta

Plotted by ERJ Mar. 1961

Inked by ERJ Mar. 1961

Checked by R.C. April, 1961

Revised 2-21-63 S.A.B.  
to show R&B structures.

23-503-6282

