4915


Borderland Spur, Crowford Spur, and Central Spur Drains
1959 Condition Profiles
Surveyed Apr. 1959
Surveyed Aug. 29-30, 1956
Field Book 1956-57, 1958-A
23-303-6018
Borderland Spur Drain
Crowford Spur Drain
Central Spur Drain
Elevations are based on U.S.C.&G.S. datum
Bench Mark #1
Top Conc. Hdwl. Ext. Drawing Lot Frame over Head Drain
Elev. 3709.89
Bench Mark #2
Top Conc. Hdwl. Ext. Embankment Drain South Side El. Pond Co. Road
Elev. 3717.64
Bench Mark #3
Top R.R. Cap Conc. Loading Platform 200 ± Feet Southeast of Mine Road
Elev. 3727.10
Bench Mark #4
Top R.R. Cap Conc. Mine Drain - East Side Drain & North Side Mine Road
Elev. 3727.10
Bench Mark #5
Top S. Conc. Hdwl. Ext. Frame over Head Drain - Elev. 3715.06
Note: Clean to original construction grade.
Note: Clean to natural stream grade.
Note: Clean to natural canopy grade.
Note: Concrete box drain. Lining thickness not checked. See details on drawing.
LEGEND
Existing Ground Elevation
Bottom of Drain
Original Construction Grade
Natural Surface Elevation