High water surface

Bottom of drain

3540

3530

0+00=356+50 Tamilla Drain

2+43 ℄ 6"CMP Drain Inlet-Lt.

Construction Grade

Elevation grade

0

10

ISLAND DRAIN

CONDITION PROFILE 1960

Surveyed by Smith, Apr. 1960

Notes recorded in Tsleia Field Book 3126

Plotted by-ERJ

Check by-JH

23-503-6155

MIAMI OWAT

CONDITION PROFILE

23-503-6155

CHARLES BRUNING COMPANY

PLAN PROFILE PLATE A