



B.M. Elev. 3573.82 Brass rod set in right upstream corner
of Hansen Lateral heading



HANSEN LATERAL

1960 CONDITION PROFILE

Surveyed by: Taylor Sept. 30 - Oct. 4, 1960
Notes in Field Book 3153.8 3146 Ysiera
Plotted by: J.G.H. Jan. 1961
Inked by: E.R.J. Feb. 1961
Revised 3-6-63 S.P.
To show R&B structures
23-503-6245.



HANSEN LATERAL

1960 CONDITION PROFILE

Surveyed by: Taylor Sept. 30 - Oct. 4, 1960
Notes in Field Book 3153.8 3146 Ysiera
Plotted by: J.G.H. Jan. 1961
Inked by: E.R.J. Feb. 1961
Checked by:
Revised 3-6-63 S.P.
To show R&B structures
23-503-6245.