

B.M. Elev. 3571.65 Brass Cap on check walkway at Sta. 70+94
of the I-154 Lateral.

- LEGEND
- Right Bank
 - Left Bank
 - Bottom of Lateral
 - High Water in Lateral
 - High Water at end of Lateral
 - Natural Surface

I-136 LATERAL
CONDITION PROFILE

1970
Surveyed by D. Rush F. B. 3211
Plotted by E.R.J.
23 503 7391
Checked by JEM

