


B.M. Elev 3562.78 On brass cap in top of downstream head wall of I-341 heading.

- LEGEND
- Right Bank
 - Left Bank
 - High Water in Lateral
 - High Water at End of Turnout
 - Bottom of Lateral
 - Natural Surface Lateral Rt.

I-341 LATERAL CONDITION PROFILE 1961

Surveyed by Taylor Jan. - Feb. 1961
Notes in Field Book 3169 1st ed.
Plotted and linked by ERJ Aug. 1961
Checked by JH
Revised 3-7-63 S.P.
To show R&B structures
23-503-6384



I-341 LATERAL CONDITION PROFILE 1961.

Surveyed by Taylor Jan. - Feb. 1961
Notes in Field Book 3169 1st ed.
Plotted and linked by ERJ Aug. 1961
Checked by JH
Revised 3-7-63 S.P.
To show R&B structures

23-503-6384.