
B.M. Elev. 3561.01 ⊕ Cut Rt. upstream cor. hdwl. of T.O. I-270 W.W. -
Sta. 20+45 - Island Farmers Drain

LEGEND
- Bottom of Ditch
- Top of Lt. Bank
- Top of Rt. Bank
- Natural Surface Lt. & Rt.
- Water Surface Elevation



Island Farmers Drain
1960 Condition Profile

Surveyed Taylor Dec. 1960
Field Book 3074 Yrietz
Plotted R.C. June 1962
Checked

23-503-6637

Note: Clean to adopted cleaning grade

B.M. 3576.85 ⊕ Cut Rt. rail check at 1+54 Lat. Hdwg. -
Sta. 154+31 - Island Main Lat.



Island Spur Drain
1960 Condition Profile

Surveyed Taylor Dec. 1960
Field Book 3074 Yrietz
Plotted R.C. June 1962
Checked

Note: Clean to indicated cleaning grade

THAYNOD BRIDGES ELSEARO