

B.M. Elev. 3583.75 Top of upstream rail of Crismore Lateral heading.

- LEGEND
- Right Bank
 - Left Bank
 - Right Top of Lining
 - Left Top of Lining
 - High Water Surface
 - Bottom of Lateral

CRISMORE LATERAL

CONDITION PROFILE 1959

SURVEYED BY SMITH 10-13-59

FIELD BOOK, 3078 YSLETA.

PLOTTED BY, E.R.J. 7-23-62.

CHECKED BY

Revised 2-20-63 S.A.B.
to Show R&B Structures.

23-503-6690

