

B.M. Elev. 3609.92 Top of 2nd rail from right of concrete  
check at Sta. 1098+65 of the Franklin Canal.

# LEGEND

-  Top of bank - Lt.
-  Top of bank - Rt.
-  Top of lining - Lt.
-  Top of lining - Rt.
-  Elevation of high water surface in lateral.
-  Elevation of high water surface at exit of T.O.
-  Bottom of lateral

## SALITRAL LATERAL

### CONDITION PROFILE 1960

Surveyed by: Smith March 1960.

Field books: 3119, 3120 & 3121 Ysleta

Plotted by: J. H. Oct. 1960

Checked: L.C.

Revised 2-18-63 S.P.

To show R & B Structures

23-503-6195

Bottom and  $\phi$  of  
The Franklin Canal

