

upstream cor. concrete check at sta. 315+79 Franklin Canal.

Canal
End of Turnout.
e Lining-Rt.
e Lining-Lt.

FRANKLIN CANAL (Sta. 315+79 to 1209+91) CONDITION PROFILE 1961

Surveyed by Taylor Jan.-Feb. 1961
Notes in Field Books 3164-65-66-67 Ysl.
Plotted & Inked by E.R.J. Jul. 1961.
Checked by R.C. Aug. 1961.
Revised 3-6-63 S.A.B.
to show R & B Structures.

23-503-6381.

310 320 330 340 350 360 370

