

Sta. 548+73 # Maste-way No 2 Rt.
 Sta. 548+94 Face of Conc. check. 7-5' bays
 Sta. 548+94 Face of 10 Lat. Hdg.
 36" 5/8" Conc. pipe
 Sta. 549+78 End of check lining

91.80

~~Sta. 554+71 TO Rt. 2. side gate conc. pipe~~ / ~~Removed~~

~~Sta. 562+81 Timber Bridge 16x56~~ / ~~Removed~~
 Sta. 562+98 T.O. Rt. (S.G.) 24 conc. pipe
 18"

CANAL BOTTOM Nov. 3, 1964

Sta. 587+00 Rvstd. Canal = Sta. 0+00 Rvstd. Canal Ext.

Sta. 0+20 Island main heading Rt. 4-6' bay skimming weir
 Sta. 0+20 Enter Island Feeder Lt.
 Sta. 0+20 Heading. 3-4' bays
 Sta. 0+43 Face concrete check. 5-5' bays
 Sta. 0+53 Timber bridge 16x55'
 Outlet San Elizario WW #2 beneath bridge
 Sta. 1+16 End check lining
 Sta. 3+08 Meter Bridge, timber, suspension

Canal bottom
 cleaning

550

560

570

580

590

0+00

3590.10

3568.90

3579.50

3567.00

3560'

3570'

3580'

3577.42