

B.M. Elev. 3737.45 Channon Singh Flume,
Sta. 47+60, East Drain.

3750
0+00 Anthony Drain = 48+07 East Drain.
3740

N.S.
Lt. Rt.

N.S.
Lt. Rt.

N.S.
Lt. Rt.

N.S.
Lt. Rt.

N.S.
Lt. Rt.

43+86 36"x60' CMP Culvert

17+65 & Texas Lateral

17+40 End
36"x60' Conc. Pipe Culv.
18+00 Entrance

$s = .00065$ Original Construction Grade

CLEANING GRADE $s = .00077$

Note:-
Clean to original construction
except where cleaning grade is inc

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF RECLAMATION

RIO GRANDE PROJECT-NEW MEXICO-TEX.

ANTHONY DRAIN CONDITION PROFILE 1958

Plotted and inked E.R.J. Sept. 5, 1958.

Checked R.S. Surveyed June 25-July 1958.

Field Book A-18E 1958.

23-503-5955

(FILED V-68)

3720

0

10

20

30

40

Cleaned October 1958
" April 1962

Cleaned April 1962
0+00 to 90+00