

53-203-e207
CONDITION PROFILE 1961
BORDER INTERCEPTING DRAIN

B.M. Elev. 3549.76 Brass Cap Top of Inlet
Headwall Sta. 71+25 Island Drain

0+00 Border Intercepting Drain
= 72+30 Island Drain

- LEGEND
- Bottom of Drain
 - Natural Surface Elevation
Left and Right
 - Water Surface Elevation

BORDER INTERCEPTING DRAIN

Surveyed: Smith July 1960
Field Book: 3151
Plotted: S.P.
Checked: *[Signature]*

23-503-6507

3550

3540

3530

0+52 6' 36" x 64' CMP Culv. - Form Road

0+00 = 72+30 Island Drain

Elev. 3532.9

16+71 Metering Bridge

S=.0093

Bottom Island Drain

Cleaning grade on Island Drain = 3531.72

Cleaning grade

S=.0006

Note: Clean to indicated grade.

0

10

20

30

14'-8" long