Borderland Spur, Crawford Spur, and Central Spur Drains

1959 Condition Profiles

Plotted and Inked: R.C.
Checked: S.B. May, 1959
Surveyed: May 5 - 18, 1959
Field Book: 1959-D – File 15-G

23-503-6019

Legend
Water Surface Elevation
Bottom of Drain
Original Construction Grade
Natural Surface Elevation
B.M. Elev. 3709.69 Top Conc. Hd'wl. Ent. Stevens Lat. Flume over West Drain.
B.M. Elev. 3717.64 Top N.W. Cor. Conc. Lining End Borderland Drain South Side El Paso Co. Road.
B.M. Elev. 3707.02 Top ℄ 12" CMP W.W. into West Drain - East Side drain & North side Farm Road (Sta. 95+00).
B.M. Elev. 3723.49 Top ℄ Conc. Hd'wl. Ent. Flume over West Drain - Sta. 249+39.
Borderland Spur Drain
Crawford Spur Drain
Central Spur Drain
Elev. 3696.6
0+15 Exit 24" x 127' PCP Culvert 1+42 Entrance
107+04 Exit 10' Transition
S = .0008
S = .0015
Note: Clean to original construction grade.
3690
3700
3710
3720

Borderland Spur, Crawford Spur, and Central Spur Drains

1959 Condition Profiles

Plotted and Inked: R.C.
Checked: S.B. May, 1959
Surveyed: May 5 - 18, 1959
Field Book: 1959-D – File 15-G

23-503-6019