

B.M. Elev. 3737.72 on brass plate east side
concrete check Station 0+00 Wasteway 23A =
Station 99+76 end Texas Lateral.

W.W. 23A 0+00 - 0+67

LEGEND

- Natural Surface Rt. and Lt.
- Water Surface
- Original Construction Grade
- Bottom of Drain

3750

3740

3730

3720

Bottom of Rio Grande
W.S. in Rio Grande
River bank

0+00 = Original Stationing
0+30 1.B.C. East Levee
2 span trestle - 14' x 48'
0+70 End W.W. 23A
Texas Lateral Rt.

8+20 Arroyo enters Lt.

26+50 Arroyo enters Lt.

Elev. 268

-(3+00)

0

10

20

30

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF RECLAMATION
RIO GRANDE PROJECT - N. MEX. - TEX.

EAST DRAIN 1958 CONDITION PROFILE

Plotted and Inked: R.S. Oct. 2, 1958
Checked: E.R.J.

Field Books 16F-1958 A & B
Surveyed April 25 - May 28, 1958

(Filed R-66V)

23-503-5962