




ISLAND DRAIN CONDITION PROFILE

Surveyed by Smith Apr. 19

Notes recorded in Ysleta Field

Plotted by ERJ Au

Checked by JH