

B.M. Elev. 3627.31 Top rt. rail check
Sta. 131+31 Juan de Herrera Br. B.



MESA SPUR DRAIN 1958 CONDITION PROFILE

Surveyed: Oct. 15 - Nov. 6 - 1958
Field Book: 3071
Plotted & Inked: R.S. Dec. 1958
Checked: E.R.J.

23-503-5989