

LEGEND
- - - Right Bank
- - - Left Bank
- Natural Surface Lt & Rt
o Water Surface
Bottom of Drain

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF RECLAMATION
RIO GRANDE PROJECT - N. MEXICO - TEXAS
PLAYA DRAIN
CONDITION PROFILE 1960
SURVEYED BY SMITH & REDMAN JAN., FEB. & MAR. 1960.
NOTES IN FIELD BOOK 3106 YSLETA
PLOTTED BY: E.R.J. 4-8-60
CHECKED BY: R.C.

23-503-6097.

