

B. M. Elev. 3623.17 Top right rail of check at sta. 118+61 Playa Drain.

LEGEND

- Left bank
- Right bank
- Water surface
- Natural surface left and right
- Bottom of drain

0+00 = 40+46 & Playa Drain

Right bank  
Left bank

33+92 & 24"x66' CMP Farm Flume

40+50 & 18"x70' CMP flume

UNITED STATES

DEPARTMENT OF THE INTERIOR  
BUREAU OF RECLAMATION

RIO GRANDE PROJECT-NEW MEXICO-TEXAS

PLAYA INTERCEPTING DRAIN

CONDITION PROFILE 1960

Surveyed by Smith 2-1-60, 2-4-60.

Surveyed by Redman 3-9-60, 3-11-60.

Notes recorded in field book 2365 p. 41-46.

and field book 3117 Ysleta.

Plotted by E.R.J. Apr. 1960

Checked by E.C.

23-503-6102.

3610

Elev. 3611.0

Elev. 3608.6

3600

0

10

20

30

40

cleaning grade  $S = .0007$

Note: clean to