

B.M. Elev. 3566.41 Brass cap top and left upstream corner of lining of Tornillo Heading.

LEGEND

- Right Bank
- Left Bank
- Water Surface
- Natural Surface
- left and right
- Bottom of drain.

RIVER DRAIN OUTLET
AND
RIVER DRAIN
CONDITION PROFILE
1959

Surveyed by Smith Oct.- Nov. 1959
Field books 3095, 3096 and 3098 - Ysleta
Plotted by E.R.J. Dec. 1959
Checked by: R.C. Jan. 1960

