288+06 Tel.& Elect. Lines Overhead Elev. 3604.6
289+46 ℄ Farm Road
293+53 24"x 75' CMP Farm Flume
289+16 Exit
36"x 54' CMP Culvert
289+70 Entrance
Elev. 3575.9
314+18 Tel.& Elect. Lines Overhead Elev. 3611.8
320+53 ℄ Campbell Road
320+83 Tel. & Elect. Lines Overhead Elev. 3605.4
329+51 ℄ 42"x 60' CMP Culvert Farm Road
345+55 ℄ 36"x 74' CMP Culv.- Chicken Ranch Rd.
346+68 ℄ 48"x 100' CMP Flume San Elizario Lateral
Cleaning grade, S=.00055.
Note: Clean to indicated cleaning grade.
320+16 Exit
36"x 76' CMP Culvert
320+92 Entrance
Note: From station 320+92 to end of drain plotting is from field notes transcribed from Ysleta F.B. 3096 & 3098 in order to correct stationing.
382+92 ℄ Timber Bridge 16'x 50' Las Pompas Road
℄ N.S
390+88 - 8" Galv. Pipe Inlet
393+26 - 10" CMP Inlet
394+61 Salt : 110
383+22
403+22 END OF NEW CMP
416+16 Wash-in Rt.
416+68 ℄ Road 30"x 72' PCP in fill Las Canas Agrias Lateral Crossing
422+14 Tel. & Elect. Overhead Lines Elev. 3619.9
423+64 Tel. & Elect. Overhead Lines Elev. 3611.9
424+04 ℄ Farm Flume (24"x 50') + (20"+72') CMP
424+16 ℄ Timber Bridge
Elev. 3582.4
416+37 Exit
36"x 74' CMP Culvert
417+11 Entrance
436+26 Azucena
440+03 Wash-in Lt.
441+69 ℄ 24"x 60' CMP Farm Flume
441+94 Wash-in Lt.
449+32 ℄ Timber Bridge 16'x 52'
457+30 ℄ 30" CMP Farm Flume
Cleaning grade, S=.00113
469+42 ℄ 30"x 98' CMP in Farm Ditch
469+58 ℄ Farm Road Perez
N.S. Rt
469+10 Exit
36"x 72' CMP Culvert
469+82 Entrance
478+12 Timber Bridge 15'x 48'
478+25 ℄ 24"x 102' CMP Farm Flume
479+18 Wash-in Rt or Lt?
Elev. 3589.6
HOR SCALE 1" = 500'
VERT 1" = 5'
Cleaning grade, S=.00113
484+21 ℄ San Elizario W.W.
484+66 Tel. & Elect. Overhead Lines Elev. 3624.5
T.B. T.B.
Elev. 3590.0
483+91 Exit
2.5'x 3.5'x 75' Conc. Box Culv.
484+66 Entrance
491+86 ℄ Farm Flume 18" CMP
492+03 ℄ Farm Bridge 13'x 61'
514+22 ℄ 36"x 54' CMP Culvert - Farm Road Saleido
Cleaning grade, S=.00033
Note: Clean to indicated cleaning grade.
546+95 ℄ Road
546+77 Exit
30"x 40' PCP Culvert
547+17 Entrance
557+78 ℄ 18"x 80' CMP Farm Flume
557+85 ℄ Farm Road
Elev. 3592.4
557+53 Exit
30"x 62' CMP Culvert
558+15 Entrance
566+88 ℄ Farm Ditch
567+05 ℄ Road Valle Romero
566+68 Exit
24"x 60' CMP Culvert
567+28 Entrance
577+87 Walcott
Cleaning grade, S=.00055
581+92 ℄ 24"x 105' CMP Farm Flume (dwg. 23-503-6365 R&B 1962)
582+00 ℄ Timber Bridge 16'x 52'
586+37 ℄ Road
586+17 Exit
30"x 59' CMP Culvert
586+76 Entrance
609+25 ℄ Road
Elev. 3595.2
609+00 Exit
24"x 47' CMP Culvert
609+47 Entrance
Cleaning grade, S=.001
641+10 ℄ 30"x 121' CMP Siphon
641+29 ℄ Farm Road (Webb Road)
640+96 Exit
30"x 77' CMP Culvert
641+73 Entrance
End of Drain
Elev. 3601.3
3570
3580
3590
3600
3610
290
300
310
320
330
340
350
360
370
380
390
400
410
420
430
440
450
460
470
480
490
500
510
520
530
540
550
560
570
580
590
600
610
620
630
640
650
660
670

RIVER DRAIN
CONDITION PROFILE 1959
SURVEYED BY SMITH OCT-NOV. 1959
PLOTTED BY E.R.J. FEB. 1960 FROM
YSLETA FIELD BOOK 3095 AND 3096
3098 TRANSCRIBED TO CORRECT
STATIONING.
CHECKED BY, R.C.

23-503-6078