

B.M. Elev. 3522.30 Brass cap set top left upstream corner of Hudspeth Heading.

LEGEND
— Natural surface left and right
— High water surface
— Bottom of drain.

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF RECLAMATION

TORNILLO DRAIN

CONDITION PROFILE 1960
Surveyed by Smith, April 1960
Notes recorded in Ysleta Field Book #3123
Plotted by ERJ May 24, 1960.
Checked by J.H.

23-503-6113

