

B.M. Elev. 3602.53 Brass cap on left end of walk slab on check at Sta. 0+00 Cañas Agrías Lateral.

- LEGEND
- Right bank
 - Left bank
 - High Water Surface
 - High Water - End of Turnout
 - Bottom of Lateral

CAÑAS AGRÍAS LATERAL
CONDITION PROFILE 1960

Surveyed by Smith 5/20/60
Notes in field book 3127 Ysleta
Plotted by SAB 5/11/62
Inked by SAB 5/2/62
Checked by *[Signature]*
Revised 2-27-63 SAB
to show K&B Structures.

23-503-6620

