

Exhibit A

B.M. Elev. 3562.78 On brass cap in top of downstream headwall of I-341 heading.

LEGEND

- Right Bank
- - - Left Bank
- o— High Water in Lateral
- x- High Water at End of Turnout
- Bottom of Lateral
- - - Natural Surface Lt. and Rt.

I-341 LATERAL CONDITION PROFILE 1961

Surveyed by Taylor Jan.-Feb. 1961

Notes in Field Book 3169 Ysleta.

Plotted and inked by ERJ Aug. 1961

Checked by JH

Revised 3-7-63 S.P.

To show R & B structures

23-503-6384

