

B. M. Elev. 3639.11 Top left rail of check at sta. 694+73
Franklin Canal

LEGEND

- Top of lining - left
- Top of lining - right
- Top of bank - left
- Top of bank - right
- Water surface elevation
- Water surface elevation at end of turnout
- Bottom of lateral

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF RECLAMATION
RIO GRANDE PROJECT-NEW MEXICO-TEXAS

JORNADO LATERAL CONDITION PROFILE 1960

Surveyed by Smith May 1960
Notes recorded in Field Book 3125
Plotted by E. R. J.
Checked by J. H.

Revised 1-17-'63 - R.C.
to show R. & B. Structures

23-503-6144

