

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF RECLAMATION  
RIO GRANDE PROJECT-NEW MEXICO-TEXAS

**JORNADO LATERAL**  
CONDITION PROFILE 1960

Surveyed by Smith May 1960  
Notes recorded in Field Book 3125  
Plotted by E. R. J.  
Checked by J. H.

Revised 1-17-63 - D.C.  
to show R & B Structures

23-503-6144

B. M. Elev. 3639.11 Top left rail of check at sta. 694+73  
Franklin Canal

**LEGEND**  
Top of lining - left  
Top of lining - right  
Top of bank - left  
Top of bank - right  
o Water surface elevation  
-x- Water surface elevation at end of turnout  
Bottom of lateral

