

B.M. Elev. 3713.45 Brass plate on check at
Sta. 107+82 Montoya Main Lateral.

LEGEND
- - - Right bank
- - - Left bank
○ High Water Surface
-x- High Water, end of turnout
- Natural Surface, left and right
} Bottom of lateral

MONTOYA LATERAL "A" CONDITION PROFILE 1962

Surveyed by Redman 5-2-62

Field Book No. 13-P, File 1961-H, Las Cruces

Plotted by S.A.B.

Checked by R.C.

23-503-6634

