


B.M. Elev. 3713.45 Brass plate on check at Sta. 107+82 Montoya Main Lateral.

LEGEND
Right bank
Left bank
High Water Surface
High Water, end of turnout
Natural Surface, left and right
Bottom of lateral

MONTOKA LATERAL "A"
CONDITION PROFILE 1962

Surveyed by Redman 5-2-62
Field Book No. 13-P, File 1961-H, Las Cruces
Plotted by S.A.B.
Checked by R.G.

23-503-6634



3700
3699
3698
3697
3696
3695
3694
3693
3692
3691
3690

3710