

0 1/2 8'

400 BE-213 2/17/13
3007 10/11

www.dynaproject.com
DYNAPROJECT
3007 10/11


400 BE-213 2/17/13
3007 10/11

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF RECLAMATION
RIO GRANDE PROJECT-NEW MEXICO-TEXAS
UPPER CLINT LATERAL
CONDITION PROFILE-1960
Surveyed by J. Smith, June 1960
Field notes recorded in Book 3130 Yuleta
Plotted by J.H. May, 1960
Checked by *CHG*
23-503-6153

LEGEND
- - - Right Bank
- - - Left Bank
+ High Water Surface
+ High Water At End Of T.O.
- Bottom of Lateral

B.M. Elev 3634.0 Top of right rail of check in
San Elizario Lateral at Sta 8+72

3600



7+57 18" S.G. T.O.-Lt.

13+90 12" S.G. T.O.-Lt.

24+53 12" S.G. T.O.-Rt.