

B.M. Elev. 3613.40 Top of right rail of check in
San Elizario Lateral at Sta. 8+72

LEGEND
 - - - Right Bank
 - - - Left Bank
 o High Water Surface
 x High Water At End of T.O.
 / Bottom of Lateral

UNITED STATES
 DEPARTMENT OF THE INTERIOR
 BUREAU OF RECLAMATION
 RIO GRANDE PROJECT-NEW MEXICO-TEXAS

UPPER CLINT LATERAL CONDITION PROFILE-1960

Surveyed by J. Smith, June 1960
 Field notes recorded in Book 3130 Ysleta
 Plotted by J.H. Aug. 1960
 Checked by *ERJ*

23-503-6153

